



CORS USERS FORUM

Real Time GNSS Networks


Tennessee DOT

Jim Waters, PE, RLS

Assistant Director TDOT Design Division



CGSIC CORS USERS FORUM
Savannah, Georgia




TDOT GNSS Reference Network


- 22 GNSS Reference Stations
 - All National CORS
 - Aligned to NSRS
- 2 GNSS Reference Stations
 - Submitted to NGS for National CORS Inclusion.
- 20 Proposed GNSS Stations
 - Planned National CORS Sites.
 - Possible Mount Change
- Additional GNSS Stations T.B.D.



TDOT GNSS Reference Network



TDOT GNSS Reference Network (With Proposed Stations)



TDOT GNSS Reference Network

- Hardware Components
 - GNSS Receiver
 - Topcon Net G3 Receivers
 - GNSS Antenna
 - Topcon G3 A1 Antennae
 - Mounting Bracket
 - Custom Steel Brackets
 - Cables
 - Times Microwave LMR 400 (<50 meters) and LMR 600 (>50 meters).



TDOT GNSS Reference Network

- Hardware Components
 - Servers
 - One data storage server
 - One network access server
 - IT Network
 - All receivers connected behind firewall to TDOT IT Infrastructure.
 - Connected to 100 mbps switches.
 - Uninterrupted Power Supply
 - In-Line Lightning Protection



TDOT GNSS Reference Network

- Software Components
 - Topcon TopNET Software
 - **TopNET-S** is the server component which manages reference stations.
 - **TopNET-V** is the network correction software for both single base line solutions and modeled network solution.
 - **TopNET-R** is the remote user component for monitoring receivers and changing receiver configurations.
 - **TopNET Web** is the web interface for network information.
 - **Download Center** is responsible for downloading all raw data files.



TDOT GNSS Reference Network

TopNET-5 0.0.0.0:8000


File Setup View Help

Date Start	Send	Receiver	User	Task	Address	Interface	Messages
9/15/2008 10:3...	23053...	TN43	jjvp210	TopNET-V	12.189.231.51...	TCP 10.165.1...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 10:3...	23579...	TN35	jjvp210	TopNET-V	12.189.231.51...	TCP 10.173.8...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 10:3...	23183...	TN25	jjvp210	TopNET-V	12.189.231.51...	TCP 10.185.2...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 10:3...	23635...	TN33	jjvp210	TopNET-V	12.189.231.51...	TCP 10.174.9...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 10:3...	21067...	TN23	jjvp210	TopNET-V	12.189.231.51...	TCP 10.182.2...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 10:3...	23453...	TN15	jjvp210	TopNET-V	12.189.231.51...	TCP 10.190.1...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 10:3...	23346...	TN24	jjvp210	TopNET-V	12.189.231.51...	TCP 10.181.2...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 10:3...	23742...	TN37	jjvp210	TopNET-V	12.189.231.51...	TCP 10.177.2...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 10:3...	22418...	TN14	jjvp210	TopNET-V	12.189.231.51...	TCP 10.195.1...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 10:3...	22191...	TN36	jjvp210	TopNET-V	12.189.231.51...	TCP 10.176.8...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 10:3...	18274...	TN11	jjvp210	TopNET-V	12.189.231.51...	TCP 10.198.1...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 6:50:53	1893...	TN23	jj01307	TopNET-R	10.170.144.54...	TCP 10.182.2...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:53	1920...	T338	jj01307	TopNET-R	10.170.144.54...	TCP 10.174.9...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:53	1936...	TN37	jj01307	TopNET-R	10.170.144.54...	TCP 10.177.2...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:53	1944...	TN31	jj01307	TopNET-R	10.170.144.54...	TCP 10.171.5...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:53	1867...	TN32	jj01307	TopNET-R	10.170.144.54...	TCP 10.180.6...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 10:3...	22785...	TN38	jjvp210	TopNET-V	12.189.231.51...	TCP 10.183.6...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 11:4...	16823...	TN32	jj01307	TopNET-V	10.170.145.31...	TCP 10.180.6...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 10:3...	22407...	TN34	jjvp210	TopNET-V	12.189.231.51...	TCP 10.178.1...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 10:3...	23856...	TN31	jjvp210	TopNET-V	12.189.231.51...	TCP 10.171.5...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 10:3...	22626...	TN22	jjvp210	TopNET-V	12.189.231.51...	TCP 10.187.1...	jps/RD:10,UO:1.0,SI:10,PO:10,GE:1.0,NE:1.0,rM:1...
9/15/2008 6:50:51	1916...	TN12	jj01307	TopNET-R	10.170.144.54...	TCP 10.196.6...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:51	1849...	TN11	jj01307	TopNET-R	10.170.144.54...	TCP 10.198.1...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:51	1916...	TN44	jj01307	TopNET-R	10.170.144.54...	TCP 10.167.6...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:51	1912...	TN36	jj01307	TopNET-R	10.170.144.54...	TCP 10.176.8...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:51	1916...	TN14	jj01307	TopNET-R	10.170.144.54...	TCP 10.195.1...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:51	1919...	TN22	jj01307	TopNET-R	10.170.144.54...	TCP 10.187.1...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:51	1934...	TN35	jj01307	TopNET-R	10.170.144.54...	TCP 10.173.8...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:51	1936...	TN33	jj01307	TopNET-R	10.170.144.54...	TCP 10.174.9...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:51	1932...	TN15	jj01307	TopNET-R	10.170.144.54...	TCP 10.190.1...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:51	1922...	TN38	jj01307	TopNET-R	10.170.144.54...	TCP 10.183.6...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:51	1930...	TN25	jj01307	TopNET-R	10.170.144.54...	TCP 10.185.2...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:51	1932...	TN24	jj01307	TopNET-R	10.170.144.54...	TCP 10.181.2...	jps/UO:1.0,SI:2,PV:2,rE:2,
9/15/2008 6:50:51	1924...	TN41	jj01307	TopNET-R	10.170.144.54...	TCP 10.168.5...	jps/UO:1.0,SI:2,PV:2,rE:2,


9/15/2008 19:00:44 TN11 > RE004%em%
 Client=10.170.144.54:58373 < Rcv=1 RE:OK. Send=2250085
 Client=10.170.144.54:58373 < Rcv=0 CloseUsr
 Client=10.170.144.54:58373 < Rcv=0 RE:OK.
 Client=jj01307/10.170.144.54:58373 (Download_Center) thread terminated




CGSIC CORS USERS FORUM
 Savannah, Georgia



TDOT GNSS Reference Network



CGSIC CORS USERS FORUM
Savannah, Georgia



TDOT GNSS Reference Network

TopNET-R @ 10.170.145.31

Connection Tools View PC Clock Sync Setup Help

Name	SVs (GPS+GLONASS)	Latitude	Longitude	Elev. Ht. (m)	Last Epoch (GPS)	Latency (ms)
T338	9+6	36°33'31.39749"N	87°19'09.99959"W	135.4221	1497:2 00:14:18	1522
TN11	8+2	36°21'42.04840"N	82°23'33.93635"W	449.0145	1497:2 00:14:18	1912
TN12	8+6	36°14'53.02986"N	83°17'11.08060"W	336.1011	1497:2 00:14:18	1896
TN13	8+7	35°56'37.12277"N	83°12'26.42406"W	359.4972	1497:2 00:14:18	1912
TN14	7+6	36°24'27.39746"N	84°03'54.63992"W	328.4646	1497:2 00:14:18	1896
TN15	8+7	36°00'08.32504"N	83°46'13.95961"W	270.3026	1497:2 00:14:18	1912
TN16	8+6	35°54'09.89101"N	84°36'04.37101"W	216.7291	1497:2 00:14:18	1928
TN21	8+6	35°03'51.82818"N	85°12'25.93956"W	195.8962	1497:2 00:14:18	1896
TN22	9+6	35°23'25.81626"N	85°22'40.98104"W	205.7647	1497:2 00:14:18	1912
TN23	8+5	35°55'10.77690"N	84°59'57.56995"W	526.2795	1497:2 00:14:18	1896
TN24	9+7	36°08'03.78873"N	85°29'57.82572"W	308.3926	1497:2 00:14:18	1928
TN25	9+6	35°22'01.53677"N	86°11'20.78467"W	301.2888	1497:2 00:14:18	1912
TN31	9+7	36°10'13.14790"N	86°52'14.39281"W	111.9193	1497:2 00:14:18	1912
TN32	9+2	36°23'48.64576"N	86°24'19.68720"W	173.0222	1497:2 00:14:18	1896
TN33	9+7	36°33'31.40115"N	87°19'09.99306"W	135.2627	1497:2 00:14:18	1912
TN34	8+5	35°25'34.80805"N	86°42'43.88582"W	228.8560	1497:2 00:14:18	1912
TN35	9+7	36°06'14.24117"N	87°37'21.52898"W	229.8376	1497:2 00:14:18	1912
TN36	9+5	35°15'20.83087"N	87°19'33.74935"W	259.0308	1497:2 00:14:18	1912
TN37	9+7	35°36'13.84636"N	87°05'37.70310"W	192.1899	1497:2 00:14:18	1896
TN38	8+7	35°53'46.06182"N	86°26'37.29318"W	140.1434	1497:2 00:14:18	1896
TN41	8+7	36°07'34.97224"N	88°30'45.87347"W	114.9765	1497:2 00:14:18	1912
TN42	9+7	36°08'12.63905"N	89°14'53.31841"W	94.1230	1497:2 00:14:18	1928
TN43	9+7	35°13'42.94056"N	88°36'14.11240"W	120.7901	1497:2 00:14:18	1928
TN44	9+5	35°38'25.59297"N	88°55'08.63532"W	90.7943	1497:2 00:14:18	1912
TN45	8+7	35°17'57.46322"N	89°39'34.60751"W	62.3950	1497:2 00:14:18	1928

9/15/2008 19:14:02 TN45 online

UTC: 00:14:07 Local: 19:14:07


start

Novell GroupWise - Ji... Microsoft PowerPoint ... 3J00WW091 - jj00ww... C:\Documents and Se... Ps Adobe Photoshop CS... TopNET-R @ 10.170....


7:14 PM Monday 9/15/2008



CGSIC CORS USERS FORUM
Savannah, Georgia



TDOT GNSS Reference Network



TDOT GNSS Reference Network


The screenshot shows the 'Download Center' application window. The title bar reads 'Download Center - 10.170.145.31'. The interface includes a menu bar (File, Setup, Help), a toolbar, and three main panes. The top pane is a table of receivers and their states. The middle pane is a table of file transfers. The bottom pane is a log of service events.

Receiver	State
TN44	Wait until 19:30
TN43	Wait until 19:20
TN42	Wait until 20:10
TN41	Wait until 20:00
TN23	Wait until 20:10
TN25	Wait until 19:30
TN24	Wait until 19:20
TN22	Wait until 20:00
TN16	Wait until 19:50
TN15	Wait until 19:40
TN14	Wait until 19:30
TN13	Wait until 19:20
TN12	Wait until 20:10
TN11	Wait until 20:00

Original File	Current File	FTP Server	FTP Directory	State
D:\TN...	TN41-75...	ftpuser....	2008\259\...	Uploaded 26623282 bytes
D:\TN...		ftpuser....	2008\DMIT...	
D:\TN...			\	
D:\TN...		ftpuser....	2008\259\...	
D:\TN...		ftpuser....	2008\DMIT...	
D:\T33...			\	

Log of service events:

- 8/15/2008 8:02:52 Service started
- 8/15/2008 8:05:00 Time has come for T33B
- 8/15/2008 8:05:07 New file T33B0815m found on T33B
- 8/15/2008 8:05:50 File T33B0815m has been successfully downloaded from T33B
- 8/15/2008 8:07:39 No more files for download on receiver T33B
- 8/15/2008 8:10:00 Time has come for TN34
- 8/15/2008 8:10:00 Time has come for TN42
- 8/15/2008 8:10:00 Time has come for TN23
- 8/15/2008 8:10:00 Time has come for TN12
- 8/15/2008 8:10:02 New file TN120815m found on TN12
- 8/15/2008 8:10:02 New file TN230815m found on TN23
- 8/15/2008 8:10:02 New file TN340815m found on TN34
- 8/15/2008 8:10:07 New file TN420815m found on TN42
- 8/15/2008 8:10:27 File TN340815m has been successfully downloaded from TN34
- 8/15/2008 8:10:30 File TN230815m has been successfully downloaded from TN23
- 8/15/2008 8:10:33 No more files for download on receiver TN23
- 8/15/2008 8:10:33 File TN120815m has been successfully downloaded from TN12
- 8/15/2008 8:11:50 No more files for download on receiver TN12
- 8/15/2008 8:13:00 No more files for download on receiver TN34



TDOT GNSS Reference Network



- Current Phase?
 - TDOT Staff Using Network Daily for Survey Applications
 - Manufacturers have been testing with TDOT Network:
 - Topcon
 - Trimble
 - Leica
 - Eagle Point
 - Carlson

TDOT GNSS Reference Network



- Future Plans
 - Agreements with other State of TN Agencies for supplemental reference stations.
 - Public Sector User Agreement under development, planned public access scheduled for December 2008.
 - User fees will be charged to cover TDOT costs in support of public sector access.

TDOT, Topcon, & Hayes Instrument Installation Team



TDOT GNSS Reference Station

- Website:
 - <http://tdotcors.state.tn.us:8080/TopNETweb/>
- Contact Information:
 - Jim Waters, PE, RLS
 - TDOT Design Division
 - Suite 1300, James K. Polk Building
 - Nashville, TN 37243
 - (615) 741-0450
 - Jim.Waters@state.tn.us